



2009 Session

## **Exhibit 12**

**This exhibit is a booklet and it  
cannot be scanned therefore  
only the cover and table of  
content has been scanned to aid  
you in your research.  
The original exhibit is on file at  
the Montana Historical Society  
and may be viewed there.**

**Montana Historical Society  
Archives, 225 N. Roberts, Helena,  
MT 59620-1201  
Phone (406) 444-4774.**


Scanning by: Susie Hamilton

EXHIBIT 12  
DATE Jan 20, 09  
HS 6

---

## IRRIGATION IN MONTANA: A PRELIMINARY INVENTORY OF INFRASTRUCTURE CONDITION

---



Prepared by:

**PBS&J**  
1120 Cedar St  
Missoula, MT 59802

Prepared for:

**MONTANA DNRC**  
**CONSERVATION & RESOURCE**  
**DEVELOPMENT DIVISION**  
Resource Development Bureau  
P.O. Box 201601  
Helena, MT 59620

January 2009

## Table of Contents

<b>1.0 Executive Summary.....</b>	<b>1</b>
<b>2.0 Introduction .....</b>	<b>3</b>
2.1 Purpose and Scope .....	3
<b>3.0 Overview of Irrigation in Montana.....</b>	<b>4</b>
3.1 Brief History of Irrigation Water Use.....	4
3.2 Current Types of Irrigation Systems.....	7
3.3 Storage Facilities.....	8
3.4 Types of Users .....	9
3.4.1 Irrigation Organizations .....	9
3.4.2 Private Water Users.....	14
<b>4.0 Summary of Existing Information .....</b>	<b>15</b>
4.1 Introduction.....	15
4.2 United States Bureau of Reclamation Irrigation Projects .....	15
4.2.1 Bitter Root Project .....	17
4.2.2 The Buffalo Rapids Project.....	17
4.2.3 The Frenchtown Project.....	18
4.2.4 The Huntley Project .....	19
4.2.5 Lower Yellowstone Project.....	20
4.2.6 The Milk River Project .....	22
4.2.6.1 St. Mary's Diversion and Canal.....	22
4.2.6.2 The Chinook Division.....	23
4.2.6.3 The Malta Division .....	24
4.2.6.4 The Glasgow Division .....	24
4.2.7 The Missoula Valley Project.....	25
4.2.8 The Pick-Sloan Missouri River Basin Program .....	25
4.2.8.1 Crow Creek Unit .....	25
4.2.8.2 East Bench Unit .....	26
4.2.8.3 Helena Valley Unit.....	26
4.2.9 The Sun River Project .....	27
4.2.9.1 Fort Shaw Division .....	27
4.2.9.2 Greenfields Division .....	28
4.3 State Water Projects Systems .....	29
4.3.1 Ackley Lake Dam .....	31
4.3.1.1 Project Description.....	31
4.3.1.2 Project Deficiencies/Rehabilitation.....	31
4.3.2 Bair Dam .....	31
4.3.2.1 Project Description .....	31
4.3.2.2 Project Deficiencies/Rehabilitation .....	32
4.3.3 Cataract Creek Dam .....	32
4.3.3.1 Project Description .....	32
4.3.3.2 Project Deficiencies/Rehabilitation .....	32
4.3.4 Cooney Dam .....	32
4.3.4.1 Project Description .....	32
4.3.4.2 Project Deficiencies/Rehabilitation .....	33
4.3.5 Cottonwood Dam.....	33
4.3.5.1 Project Description .....	33
4.3.5.2 Project Deficiencies/Rehabilitation .....	33
4.3.6 Deadman's Basin Dam.....	33
4.3.6.1 Project Description .....	33

4.3.6.2 Project Deficiencies/Rehabilitation .....	34
<b>4.3.7 Fred Burr Dam .....</b>	<b>34</b>
4.3.7.1 Project Description .....	34
4.3.7.2 Project Deficiencies/Rehabilitation .....	34
<b>4.3.8 Frenchman Dam .....</b>	<b>34</b>
4.3.8.1 Project Description .....	34
4.3.8.2 Project Deficiencies/Rehabilitation .....	35
<b>4.3.9 Glacier Lake Dam .....</b>	<b>35</b>
4.3.9.1 Project Description .....	35
4.3.9.2 Project Deficiencies/Rehabilitation .....	35
<b>4.3.10 Matinsdale Dam .....</b>	<b>35</b>
4.3.10.1 Project Description .....	35
4.3.10.2 Project Deficiencies/Rehabilitation .....	36
<b>4.3.11 Middle Creek Dam .....</b>	<b>36</b>
4.3.11.1 Project Description .....	36
4.3.11.2 Project Deficiencies/Rehabilitation .....	37
<b>4.3.12 Nevada Creek Dam .....</b>	<b>37</b>
4.3.12.1 Project Description .....	37
4.3.12.2 Project Deficiencies/Rehabilitation .....	37
<b>4.3.13 North Fork Smith River Dam .....</b>	<b>37</b>
4.3.13.1 Project Description .....	37
4.3.13.2 Project Deficiencies/Rehabilitation .....	38
<b>4.3.14 Nilan Dams .....</b>	<b>38</b>
4.3.14.1 Project Description .....	38
4.3.14.2 Project Deficiencies/Rehabilitation .....	38
<b>4.3.15 Painted Rocks Dam .....</b>	<b>38</b>
4.3.15.1 Project Description .....	38
4.3.15.2 Project Deficiencies/Rehabilitation .....	39
<b>4.3.16 Ruby Dam .....</b>	<b>39</b>
4.3.16.1 Project Description .....	39
4.3.16.2 Project Deficiencies/Rehabilitation .....	39
<b>4.3.17 Tongue Rive Dam .....</b>	<b>40</b>
4.3.17.1 Project Description .....	40
4.3.17.2 Project Deficiencies/Rehabilitation .....	40
<b>4.3.18 Toston Dam .....</b>	<b>40</b>
4.3.18.1 Project Description .....	40
4.3.18.2 Project Deficiencies/Rehabilitation .....	41
<b>4.3.19 Willow Creek Dam .....</b>	<b>41</b>
4.3.19.1 Project Description .....	41
4.3.19.2 Project Deficiencies/Rehabilitation .....	41
<b>4.3.20 Yellow Water Dam .....</b>	<b>41</b>
4.3.20.1 Project Description .....	41
4.3.20.2 Project Deficiencies/Rehabilitation .....	42
<b>4.3.21 State Canal Systems .....</b>	<b>42</b>
<b>5.0 Inventory .....</b>	<b>44</b>
5.1 Overview .....	44
5.2 Mail Survey Methods .....	44
5.3 Survey Results .....	45
5.3.1 Part A of the Questionnaire .....	45
5.3.2 Part B of the Questionnaire .....	49
5.3.3 Part C of the Questionnaire .....	49

5.3.4	Part D of the Questionnaire .....	52
5.3.5	Part E of the Questionnaire .....	52
5.4	Mail Survey Discussion and Conclusions.....	54
5.5	On-site Evaluation Methods .....	55
5.6	On-site Evaluation Results.....	56
5.7	Big Ditch Company, Billings, MT.....	58
5.7.1	Diversion and Control Structure .....	58
5.7.2	Secondary Control Point.....	59
5.7.3	Snow Ditch and Diversion at 48 <sup>th</sup> and Grand Ave.....	59
5.7.4	Shiloh Walking Path Problems .....	59
5.7.5	Four Drop Points.....	59
5.7.6	Siphon at Park City .....	60
5.7.7	Benner's Check .....	60
5.8	Billings Bench Water Association, Billings, MT .....	60
5.8.1	Diversion and Control Structure .....	60
5.8.2	Large Wooden Flume.....	61
5.8.3	Tunnel through the Rims.....	62
5.8.4	Siphon Entrance .....	62
5.8.5	Rattlesnake Lake .....	62
5.8.6	Ditch Exit .....	62
5.9	Ed's Creek Water Company Pipeline, Huson, MT .....	63
5.9.1	Diversion and Control Structure .....	63
5.9.2	Pipeline .....	63
5.10	Hellgate Valley Irrigation Company Canal .....	64
5.10.1	Diversion and Control Structure .....	64
5.10.2	Urban Structures .....	64
5.10.3	Suburban Structures .....	65
5.11	Kendall Ditch Company, Lewistown, MT.....	65
5.11.1	Diversion and Control Structure .....	65
5.11.2	Crossing Nearest to Diversion .....	66
5.11.3	Bridge at Jim Philips' Property 1 .....	66
5.11.4	Active Pump Station .....	67
5.11.5	Slope Stabilization Problems .....	67
5.11.6	Home Site Access Crossing .....	67
5.11.7	Main Pumping System .....	67
5.11.8	Storage Pond near Nome Site .....	67
5.11.9	Ditch Exit .....	67
5.12	Lewistown Ditch Company, Lewistown, MT.....	67
5.12.1	Diversion and Control Structure .....	68
5.12.2	Culvert under Highway 191 .....	68
5.12.3	Urban/Suburban Encroachment Concerns .....	68
5.12.4	Trailer Park Seepage Issues .....	68
5.12.5	Old Saw Mill Seepage and Erosion Issues.....	68
5.12.6	Wolverine Creek Distribution Ditch .....	69
5.12.7	Don Jennings Erosion Issues.....	69
5.12.8	Don Jenning's Pond .....	69
5.13	North Chinook Irrigation Association, Chinook, MT.....	69
5.13.1	Diversion and Control Structure .....	69
5.13.2	North Chinook Reservoir .....	71
5.13.3	Turnouts .....	72
5.13.4	Vegetation Issues .....	72

5.14 Two Leggins Ditch, Hardin, MT .....	72
5.14.1 Diversion and Control Structure.....	72
5.14.2 Secondary Control Structure .....	73
5.14.3 Six Mile Spillway .....	73
5.14.4 Drop Structure .....	73
5.14.5 Bank Erosion Issues .....	74
5.15 Vigilante Canal Users Association, Sheridan, MT .....	74
5.15.1 Diversion and Control Structure .....	74
5.15.2 Secondary control Structure .....	74
5.15.3 Vigilante Canal System Siphons.....	75
5.15.4 Concrete and Rip Rap Drop .....	75
5.16 West Gallatin Canal Company.....	76
5.16.1 Diversion and Control Structure .....	76
5.16.2 Wilson Creek Crossing .....	76
5.16.3 Big Bear Creek Crossing.....	77
5.16.4 Cottonwood Creek Crossing .....	77
5.16.5 Dry Creek Wooden Flume .....	77
5.16.6 Middle Creek Metal Culvert Crossing .....	78
5.16.7 Trash and Week Issues.....	78
5.17 On-site Evaluation Discussion and Conclusions .....	78
<b>6.0 Infrastructure Condition and Restoration Needs.....</b>	<b>81</b>
6.1 Existing Condition of Physically Inspected Systems.....	81
6.1.1 Underlying Reasons for Conditions of Physically Inspected Systems .....	81
6.1.2 Estimated Repair Costs for Physically Inspected Systems .....	82
6.2 Existing Condition Described by Mail Survey Respondents.....	82
6.2.1 Underlying Reasons for Conditions of Mail Survey Respondents .....	83
6.2.2 Estimated Repair Costs for Mail Survey Respondents .....	83
<b>7.0 Conclusions and Recommendations.....</b>	<b>84</b>
<b>8.0 References .....</b>	<b>88</b>
<b>9.0 End Notes .....</b>	<b>91</b>